

INTERNATIONAL STANDARD

ISO
8258

First edition
1991-12-15

Shewhart control charts

Cartes de contrôle de Shewhart



Reference number
ISO 8258:1991(E)

Contents

	Page
1 Scope	1
2 Symbols	1
3 Nature of Shewhart control charts	2
4 Types of control charts	3
4.1 Control charts where no standard values are given	3
4.2 Control charts with respect to given standard values	3
4.3 Types of variables and attributes control charts	3
5 Variables control charts	4
5.1 Mean ($\bar{X}$) chart and range (R) or standard deviations (s) chart	4
5.2 Control chart for individuals (X)	5
5.3 Control charts for medians (Me)	6
6 Control procedure and interpretation for variables control charts	6
7 Pattern tests for assignable causes of variation	7
8 Process control and process capability	7
9 Attributes control charts	9
10 Preliminary considerations before starting a control chart	11
10.1 Choice of quality characteristics	11
10.2 Analysis of the production process	11
10.3 Choice of rational subgroups	11
10.4 Frequency and size of samples	12
10.5 Preliminary data collection	12
11 Steps in the construction of control charts	12
12 Illustrative examples: Variables control charts	13
12.1 $\bar{X}$ chart and R chart: Standard values given	13

© ISO 1991

All rights reserved. No part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from the publisher.

International Organization for Standardization
Case Postale 56 • CH-1211 Genève 20 • Switzerland

Printed in Switzerland