
**Optics and photonics — Preparation
of drawings for optical elements and
systems —**

**Part 18:
Stress birefringence, bubbles and
inclusions, homogeneity, and striae**

*Optique et photonique — Indications sur les dessins pour éléments et
systèmes optiques —*

*Partie 18: Biréfringence sous contrainte, bulles et inclusions,
homogénéité, et stries*





COPYRIGHT PROTECTED DOCUMENT

© ISO 2018

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
CP 401 • Ch. de Blandonnet 8
CH-1214 Vernier, Geneva
Phone: +41 22 749 01 11
Fax: +41 22 749 09 47
Email: copyright@iso.org
Website: www.iso.org

Published in Switzerland